

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/10/2016

Submitted Date:

09/24/2016

Document Number:

680101152**FIELD INSPECTION FORM**

Loc ID 392483 Inspector Name: Colby, Lou On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10026Name of Operator: VITRUVIAN EXPLORATION LLCAddress: 4 WATERWAY WAY SQUARECity: THE WOODLANDS State: TX Zip: 77380**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Colby, Lou		lou.colby@state.co.us	
molte, Shauna	(303) 422-4990	snolte@jwenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263765	WELL	PA	07/14/2005	GW	081-07092	MCINTYRE FEDERAL 3-4	RI

General Comment:

This is a Final Reclamation Inspection for PA Well API#081-07092, Spud date of 7/14/2002 by Patina O&G; Plugged & Abandoned by CDX Gas 6/14/2005. This is a Fed/Fee Location. Well received a passing FR Inspection Doc#669300182, Date 2/9/2015. Well is still noted as a Reclamation priority (Not Released); therefore Reclamation Specialist will re Inspect to Trigger Release in COGCC Files.

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: **Range Land**

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass No disturbance /Location never built _____

Access Roads Regraded Pass Contoured Pass Culverts removed Pass

Gravel removed Pass

Location and associated production facilities reclaimed Pass Locations, facilities, roads, recontoured Pass

Compaction alleviation Pass Dust and erosion control Pass

Non cropland: Revegetated 80% Pass Cropland: perennial forage _____

Weeds present Pass Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: **Location meets the Final Reclamation requirements. Vegetation cover and composition on location is sufficient and was assessed to be 80% of the surrounding area. No visible disturbance or debris remains. Dry Hole Marker installed is only evidence of this P&A Well. See Attached Photos.**

Corrective Action: _____ Date _____

Inspector Name: Colby, Lou

Overall Final Reclamation	Pass	Well Release on Active Location		Multi-Well Location	
---------------------------	------	---------------------------------	--	---------------------	--

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action: Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680101152	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962827
680101157	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962820