

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/26/2016

Submitted Date:

09/26/2016

Document Number:

675203338

FIELD INSPECTION FORM

Loc ID 334765 Inspector Name: CONKLIN, CURTIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

Findings:

18 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
TEP, Energy		COGCCInspectionReports@terraep.com	All Inspections
Giboo, David	(970) 319-2211	dgiboo@blm.com	Lead Petroleum Engineering Tech

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291988	WELL	PR	08/22/2007	GW	045-14557	FEDERAL PA 13-12	PR
292267	WELL	PR	09/17/2007	GW	045-14674	FEDERAL PA 24-12	PR
422874	WELL	PR	12/09/2013	GW	045-20636	Federal PA 413-12	PR
423056	WELL	PR	12/09/2013	GW	045-20643	Federal PA 14-12	PR
423058	WELL	PR	12/09/2013	GW	045-20645	Federal PA 523-12	PR
423059	WELL	PR	12/09/2013	GW	045-20646	Federal PA 514-12	PR
423068	WELL	PR	10/08/2013	GW	045-20653	Federal PA 324-12	PR
423070	WELL	PR	01/14/2014	GW	045-20655	Federal PA 313-12	PR
423071	WELL	PR	11/07/2013	GW	045-20656	Federal PA 424-12	PR
423073	WELL	PR	01/11/2014	GW	045-20658	Federal PA 314-12	PR
423075	WELL	PR	12/09/2013	GW	045-20660	Federal PA 423-12	PR
423078	WELL	PR	11/07/2013	GW	045-20662	Federal PA 524-12	PR
423080	WELL	PR	01/03/2014	GW	045-20663	Federal PA 513-12	PR
423084	WELL	PR	01/11/2014	GW	045-20666	Federal PA 414-12	PR
423087	WELL	PR	10/08/2013	GW	045-20668	Federal PA 23-12	PR
423099	WELL	PR	09/30/2013	GW	045-20672	Federal PA 323-12	PR

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:			
Corrective Action:			Date:
Type	SEPARATOR		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	200 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	291988	Type:	WELL	API Number:	045-14557	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ plunger								
Corrective Action:						Date:			
Facility ID:	292267	Type:	WELL	API Number:	045-14674	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ plunger								
Corrective Action:						Date:			
Facility ID:	422874	Type:	WELL	API Number:	045-20636	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ plunger								
Corrective Action:						Date:			
Facility ID:	423056	Type:	WELL	API Number:	045-20643	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ plunger								
Corrective Action:						Date:			
Facility ID:	423058	Type:	WELL	API Number:	045-20645	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ plunger								
Corrective Action:						Date:			
Facility ID:	423059	Type:	WELL	API Number:	045-20646	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ plunger								
Corrective Action:						Date:			
Facility ID:	423068	Type:	WELL	API Number:	045-20653	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ plunger								
Corrective Action:						Date:			
Facility ID:	423070	Type:	WELL	API Number:	045-20655	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ plunger								
Corrective Action:						Date:			

Facility ID: 423071	Type: WELL	API Number: 045-20656	Status: PR	Insp. Status: PR
Producing Well				
Comment: PR w/ plunger				
Corrective Action:		Date:		
Facility ID: 423073	Type: WELL	API Number: 045-20658	Status: PR	Insp. Status: PR
Producing Well				
Comment: PR w/ plunger				
Corrective Action:		Date:		
Facility ID: 423075	Type: WELL	API Number: 045-20660	Status: PR	Insp. Status: PR
Producing Well				
Comment: PR w/ plunger				
Corrective Action:		Date:		
Facility ID: 423078	Type: WELL	API Number: 045-20662	Status: PR	Insp. Status: PR
Producing Well				
Comment: PR w/ plunger				
Corrective Action:		Date:		
Facility ID: 423080	Type: WELL	API Number: 045-20663	Status: PR	Insp. Status: PR
Producing Well				
Comment: PR w/ plunger				
Corrective Action:		Date:		
Facility ID: 423084	Type: WELL	API Number: 045-20666	Status: PR	Insp. Status: PR
Producing Well				
Comment: PR w/ plunger				
Corrective Action:		Date:		
Facility ID: 423087	Type: WELL	API Number: 045-20668	Status: PR	Insp. Status: PR
Producing Well				
Comment: PR w/ plunger				
Corrective Action:		Date:		
Facility ID: 423099	Type: WELL	API Number: 045-20672	Status: PR	Insp. Status: PR
Producing Well				
Comment: PR w/ plunger				
Corrective Action:		Date:		

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Retention Ponds	Pass					
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			
Ditches	Pass	Culverts	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT