



**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:	AIRS ID 045-2111-001		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#	corrective date
Plunger Lift	# 4	
Comment:		
Corrective Action:		Date:
Horizontal Heated Separator	# 4	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		39.526360,-107.895610
Comment:	<input type="text"/>				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	<input type="text"/>			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	200 BBLS	STEEL AST		,

Comment:	Centralized battery	Date:	
Corrective Action:		Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		

Comment:	Centralized battery	Date:	
Corrective Action:		Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	YES	
Comment:	Bradenhead valves open	
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	<u>210500</u>	Type:	<u>WELL</u>	API Number:	<u>045-06256</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>286268</u>	Type:	<u>WELL</u>	API Number:	<u>045-12632</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>286269</u>	Type:	<u>WELL</u>	API Number:	<u>045-12631</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>286270</u>	Type:	<u>WELL</u>	API Number:	<u>045-12630</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>286273</u>	Type:	<u>WELL</u>	API Number:	<u>045-12629</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Plunger lift</u>								
Corrective Action:					Date:				

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:  Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
		Gravel	Pass			
		Culverts	Pass			
Gravel	Pass					
Seeding	Pass					
Slope Roughening	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT