

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/27/2016

Submitted Date:

09/28/2016

Document Number:

666802608**FIELD INSPECTION FORM**

Loc ID 334605 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268407	WELL	PR	02/20/2004	GW	045-09256	GMR 4-10 (K4B2)	PR
268408	WELL	PR	11/29/2004	GW	045-09255	GMR 4-11 (K4B2)	PR
268411	WELL	PR	01/07/2008	GW	045-09257	GMR 4-9C (K4B2)	PR

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	AIRS ID 045-0698-001		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type	#	Comment	Corrective Action	Date	corrective date
Type: Plunger Lift	# 3				
Comment:					
Corrective Action:					
Type: Pig Station	# 1				
Comment:					
Corrective Action:					
Type: Emission Control Device	# 1				
Comment:					
Corrective Action:					
Type: Gas Meter Run	# 1				
Comment:					
Corrective Action:					
Type: Vertical Heated Separator	# 3				
Comment:					
Corrective Action:					
Type: Horizontal Heated Separator	# 0				
Comment:					
Corrective Action:					

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:	Centralized battery				
Corrective Action:				Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS	
CONDENSATE	2	OTHER	STEEL AST		39.473133,107.780188	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	250bbbs	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 268407 Type: WELL API Number: 045-09256 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 268408 Type: WELL API Number: 045-09255 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 268411 Type: WELL API Number: 045-09257 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Seeding	Pass					
		Culverts	Pass			
Gravel	Pass					
		Ditches	Pass			
		Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT