

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/27/2016

Submitted Date:

09/28/2016

Document Number:

666802609

FIELD INSPECTION FORM

Loc ID 334756 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272837	WELL	PR	11/27/2004	GW	045-10175	GMR 4-10A (K4CBW)	PR
272838	WELL	PR	11/23/2004	GW	045-10174	GMR 4-6C (K4CBW)	PR
272839	WELL	PR	12/27/2004	GW	045-10173	GMR 33-15D (K4CBW)	PR

General Comment:

[Shared facilities with location ID 334586](#)

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	AIRS ID 045-0828-001		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type				corrective date
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:		Date:		
Type: Vertical Heated Separator	# 6			
Comment:				
Corrective Action:		Date:		
Type: Emission Control Device	# 1			
Comment:				
Corrective Action:		Date:		
Type: Ancillary equipment	# 1			
Comment:	vertical muffler unit			
Corrective Action:		Date:		
Type: Horizontal Heated Separator	# 0			
Comment:				
Corrective Action:		Date:		

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:	Centralized battery				
Corrective Action:		Date:			

Paint

Condition Adequate

Other (Content)

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	4	300 BBLs	STEEL AST		39.474079,-107.782021
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	
	Date:

Inspected Facilities			
Facility ID: <u>272837</u>	Type: <u>WELL</u>	API Number: <u>045-10175</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	<u>Plunger lift</u>		
Corrective Action:		Date:	
Facility ID: <u>272838</u>	Type: <u>WELL</u>	API Number: <u>045-10174</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	<u>Plunger lift</u>		
Corrective Action:		Date:	
Facility ID: <u>272839</u>	Type: <u>WELL</u>	API Number: <u>045-10173</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	<u>Plunger lift</u>		
Corrective Action:		Date:	

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Gravel	Pass					
		Gravel	Pass			
		Culverts	Pass			
Berms	Pass					
Seeding	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT