

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/28/2016

Submitted Date:

09/28/2016

Document Number:

666802611**FIELD INSPECTION FORM**

Loc ID 334623 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|-------|------------------------------|---------|
| Contact, General | | cogcc.inspections@encana.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 268811 | WELL | PR | 02/19/2004 | GW | 045-09298 | GMR 4-11C (KAC) | PR |
| 268825 | WELL | PR | 02/19/2004 | GW | 045-09300 | GMR 33-14 (K4C) | PR |
| 272936 | WELL | PR | 02/20/2004 | GW | 045-10196 | GMR 4-11BX (K4C) | PR |

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|----------------------|-------|--|
| Type | BATTERY | | |
| Comment: | AIRS ID 045-0699-001 | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | |
|--------------------|--|-------------|
| Comment: | | Date: _____ |
| Corrective Action: | | |

Overall Good: ☒**Spills:**

| Type | Area | Volume | | |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

| Type | | | corrective date |
|-----------------------------------|---------------------------|-------|-----------------|
| Type: Emission Control Device | # 0 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Vertical Heated Separator | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 0 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Chemical unit at wellhead | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tanak ID | SE GPS |
|--------------------|---------------------|----------|-----------|----------|--------|
| METHANOL | 1 | 1000 GAL | STEEL AST | | , |
| Comment: | Centralized battery | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-----------------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Contents | # | Capacity | Type | Tanak ID | SE GPS |
| CONDENSATE | 2 | OTHER | STEEL AST | | 39.474708,-107.783769 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | 250bbbs | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Inspected FacilitiesFacility ID: 268811 Type: WELL API Number: 045-09298 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 268825 Type: WELL API Number: 045-09300 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 272936 Type: WELL API Number: 045-10196 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

YES

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Ditches | Pass | | | | | |
| | | Gravel | Pass | | | |
| Gravel | Pass | | | | | |
| | | Culverts | Pass | | | |
| Seeding | Pass | | | | | |
| | | Ditches | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 666802611 | INSPECTION APPROVED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3963314 |