

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/28/2016

Submitted Date:

09/28/2016

Document Number:

684902392

FIELD INSPECTION FORM

Loc ID 317747 Inspector Name: Pesicka, Conor On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 70385
Name of Operator: SMITH ENERGY CORP
Address: 12706 SHILOH RD
City: GREELEY State: CO Zip: 80631

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Smith, Chris	303-709-6157	smithenergy@live.com	VP; North operations
Smith, Glenn	(970) 381-6253	gsmithten@what-wire.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239908	WELL	PR	10/02/1989	GW	123-07696	WELD-WEITZEL 11-33	SI

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	ajax		
Corrective Action:		Date:	
Type: Veritcal Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS

PRODUCED WATER	1	<50 BBLs	Open Top		40.529340,-104.102070
Comment: Open top, mesh cover					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity) 30bbbl					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					Date:
Corrective Action:					Date:
Contents	#	Capacity	Type	Tanak ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.529340,-104.101390
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					Date:
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					Date:
Corrective Action:					Date:
Flaring:					
Type					
Comment:					Date:
Corrective Action:					Date:

Inspected Facilities

Facility ID: 239908 Type: WELL API Number: 123-07696 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI

Corrective Action: Date:

BradenHead

Comment: Bradenhead plumbed to surface

Corrective Action: Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT