

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/28/2016

Submitted Date:

09/28/2016

Document Number:

666802612**FIELD INSPECTION FORM**

Loc ID 335063	Inspector Name: Murray, Richard	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 19 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>PO BOX 370</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>				

Contact Information:

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	Field Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257669	WELL	PR	06/23/2000	GW	045-07591	FEDERAL RMV 89-17	PR
269667	WELL	PR	04/25/2011	GW	045-09391	FEDERAL RWF 333-17	PR
281486	WELL	PR	09/14/2006	GW	045-11461	FEDERAL RWF 324-17	PR
281489	WELL	PR	01/03/2013	GW	045-11462	FEDERAL RWF 424-17	PR
281491	WELL	PR	11/21/2005	GW	045-11463	FEDERAL RWF 532-17	PR
281493	WELL	PR	09/14/2006	GW	045-11465	FEDERAL RWF 323-17	PR
281496	WELL	PR	09/14/2006	GW	045-11466	FEDERAL RWF 533-17	PR
281497	WELL	PR	11/21/2005	GW	045-11467	FEDERAL RWF 433-17	PR
281499	WELL	PR	09/14/2006	GW	045-11468	FEDERAL RWF 423-17	PR
281501	WELL	PR	11/21/2005	GW	045-11469	FEDERAL RWF 523-17	PR
281503	WELL	PR	09/14/2006	GW	045-11470	FEDERAL RMV 167-17	PR
281505	WELL	PR	11/21/2005	GW	045-11471	FEDERAL RWF 632-17	PR
285449	WELL	PR	06/30/2006	GW	045-12483	FEDERAL RWF 22-17	PR
285840	WELL	PR	07/26/2006	GW	045-12556	FEDERAL RWF 524-17	PR
285841	WELL	PR	07/26/2006	GW	045-12555	FEDERAL RWF 322-17	PR

General Comment:[Remote battery on location ID 335271](#)

LocationOverall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	AIRS ID 045-0713-002		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Horizontal Heated Separator	# 15		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 15		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 0		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	0				
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tanak ID	SE GPS	
PRODUCED WATER	1	200 BBLs	STEEL AST		39.521568,-107.908583	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Insufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	YES		
Comment:	Bradenhead valves open		
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	257669	Type:	WELL	API Number:	045-07591	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	269667	Type:	WELL	API Number:	045-09391	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	281486	Type:	WELL	API Number:	045-11461	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	281489	Type:	WELL	API Number:	045-11462	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	281491	Type:	WELL	API Number:	045-11463	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	281493	Type:	WELL	API Number:	045-11465	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	281496	Type:	WELL	API Number:	045-11466	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	281497	Type:	WELL	API Number:	045-11467	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			

Facility ID: 281499	Type: WELL	API Number: 045-11468	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID: 281501	Type: WELL	API Number: 045-11469	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID: 281503	Type: WELL	API Number: 045-11470	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID: 281505	Type: WELL	API Number: 045-11471	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID: 285449	Type: WELL	API Number: 045-12483	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID: 285840	Type: WELL	API Number: 045-12556	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID: 285841	Type: WELL	API Number: 045-12555	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass					
		Sediment Traps	Pass			
Seeding	Pass					
Sediment Traps	Pass					
Waddles	Pass					
		Culverts	Pass			
Ditches	Pass					
		Gravel	Pass			
		Ditches	Pass			

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT