


PEOC-NVG 41-23H

Inspection# 673403678

FLIR image of pop-off valve.



High resolution FLIR image of venting through tanks.

