



Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	OTHER		
Comment:	Post and Hog Wire		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Flow Line	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Natural Gas Motor and Water Transfer Equipment.		
Corrective Action:			Date:
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heater Treater	# 3		
Comment:			
Corrective Action:			Date:

Type: Gas Meter Run	# 5		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Chemical Tank on Spill Perevention		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Wellhead		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
OTHER	2	400 BBLs	STEEL AST		,
Comment:	Tank are labled as empty and are not currently in use.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)	Empty	
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS
CRUDE OIL	2	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		

Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS	
OTHER	2	300 BBLs	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content) Non-Potable Water		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS	
PRODUCED WATER	4	500 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO			
Comment:				
Corrective Action:				
				Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 209009 Type: WELL API Number: 033-06114 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT