

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/30/2016

Submitted Date:

09/30/2016

Document Number:

675203355

**FIELD INSPECTION FORM**

Loc ID 334083 Inspector Name: CONKLIN, CURTIS On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100185  
Name of Operator: ENCANA OIL & GAS (USA) INC  
Address: 370 17TH ST STE 1700  
City: DENVER State: CO Zip: 80202-

**Findings:**

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Encana,		cogcc.inspections@encana.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
279893	WELL	PR	09/01/2012	GW	077-08947	KNOX 14-6 (F14OU)	PR
281934	WELL	PR	06/05/2006	GW	077-08982	KNOX FEDERAL 14-12 (F14OU)	PR
281939	WELL	PR	07/01/2014	GW	077-08983	KNOX 14-7 (F14OU)	PR
281940	WELL	PR	06/05/2006	GW	077-08984	KNOX 14-10 (F14OU)	PR
281941	WELL	PR	06/01/2006	GW	077-08981	KNOX 14-11 (F14OU)	PR

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	4	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

<b>Inspected Facilities</b>				
Facility ID: <u>279893</u>	Type: <u>WELL</u>	API Number: <u>077-08947</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b>Producing Well</b>				
Comment:				
Corrective Action:			Date:	
Facility ID: <u>281934</u>	Type: <u>WELL</u>	API Number: <u>077-08982</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b>Producing Well</b>				
Comment:				
Corrective Action:			Date:	
Facility ID: <u>281939</u>	Type: <u>WELL</u>	API Number: <u>077-08983</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b>Producing Well</b>				
Comment:				
Corrective Action:			Date:	
Facility ID: <u>281940</u>	Type: <u>WELL</u>	API Number: <u>077-08984</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b>Producing Well</b>				
Comment:				
Corrective Action:			Date:	
Facility ID: <u>281941</u>	Type: <u>WELL</u>	API Number: <u>077-08981</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b>Producing Well</b>				
Comment:				
Corrective Action:			Date:	

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Retention Ponds	Pass					
Gravel	Pass					
Berms	Pass	Compaction	Pass			
Compaction	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT