



photo 1: Facing north toward the location.



photo 2: Facing northwest at the location.



photo 3: Facing along the southeast side along the access road. The red arrow points to noxious weeds growing in this area. Lat/Long:37.64656,-105.17977



photo 4: There were noxious weeds (Canada thistle) found at the location and along the access road.