



photo 1: The culverts along the access road had recent maintenance.



photo 2: Facing east toward the location.



photo 3: Facing toward the south side of the location.



photo 4: There were noxious weeds (Canada thistle) at the south side of the location.



photo 5: Noxious weeds (Canada thistle) were found along the north slope of the location. There were wattles displaced in this area.



photo 6: The culverts along the access road had recent maintenance.