



photo 1: Facing west along the access road toward the location.



photo 2: There were noxious weeds (Canada thistle) noticed along the access road.



photo 3: Facing northwest toward the location.



photo 4: South side of the location facing east.