

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/30/2016

Submitted Date:

09/30/2016

Document Number:

666802621

### FIELD INSPECTION FORM

Loc ID 335162 Inspector Name: Murray, Richard On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10531  
 Name of Operator: VANGUARD OPERATING LLC  
 Address: 5847 SAN FELIPE #3000  
 City: HOUSTON State: TX Zip: 77057

**Findings:**

10 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S
Axelsson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290772	WELL	PR	12/05/2007	GW	045-14197	SPECIALTY 11C-28-692	PR
291037	WELL	PR	12/04/2007	GW	045-14264	SPECIALTY 11B-28-692	PR
291038	WELL	PR	12/24/2007	GW	045-14263	SPECIALTY 11A-28-692	PR
291334	WELL	PR	12/05/2007	GW	045-14331	SPECIALTY 11D-28-692	PR

**General Comment:**

[Shared facilities with location ID 335156](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:	AIRS ID 045-1594-001		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:			

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#	Comment	Corrective Action	Date	corrective date
Emission Control Device	# 1				
Gas Meter Run	# 12				
Plunger Lift	# 4				
Ancillary equipment	# 1	Chemical unit at wellhead			
Horizontal Heated Separator	# 13				

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	8	500 BBLs	STEEL AST		39.504040,-107.675860
Comment:					
Corrective Action:				Date:	

**Paint**

Condition	Adequate
Other (Content)	

Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	YES		
Comment:	<a href="#">Bradenhead valves open</a>		
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	<u>290772</u>	Type:	<u>WELL</u>	API Number:	<u>045-14197</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>291037</u>	Type:	<u>WELL</u>	API Number:	<u>045-14264</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>291038</u>	Type:	<u>WELL</u>	API Number:	<u>045-14263</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>291334</u>	Type:	<u>WELL</u>	API Number:	<u>045-14331</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Plunger lift</u>								
Corrective Action:					Date:				

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
		Check Dams	Pass			
Ditches	Pass					
		Culverts	Pass			
Waddles	Pass					
Berms	Pass					
Seeding	Pass					
		Rip Rap	Pass			
		Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT