

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/30/2016

Submitted Date:

09/30/2016

Document Number:

666802620

FIELD INSPECTION FORM

Loc ID 335156 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
 Name of Operator: VANGUARD OPERATING LLC
 Address: 5847 SAN FELIPE #3000
 City: HOUSTON State: TX Zip: 77057

Findings:

13 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|--------------------|------------------------|
| Axelsson, Aaron | 970-230-0926 | aaxelson@vnrlc.com | Sr. Production Foreman |
| Ghan, Scott | | sghan@vnrlc.com | Sr. EH&S |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 291462 | WELL | PR | 12/18/2007 | GW | 045-14382 | SPECIALTY 21A-28-692 | PR |
| 291479 | WELL | PR | 12/20/2007 | GW | 045-14384 | SPECIALTY 24A-21-692 | PR |
| 291480 | WELL | PR | 12/19/2007 | GW | 045-14385 | SPECIALTY 21D-28-692 | PR |
| 291481 | WELL | PR | 12/20/2007 | GW | 045-14386 | SPECIALTY 24C-21-692 | PR |
| 291482 | WELL | PR | 12/18/2007 | GW | 045-14387 | SPECIALTY 21B-28-692 | PR |
| 291483 | WELL | PR | 12/18/2007 | GW | 045-14388 | SPECIALTY 21C-28-692 | PR |
| 292115 | WELL | PR | 12/20/2007 | GW | 045-14599 | SPECIALTY 14A-21-692 | PR |
| 292116 | WELL | PR | 04/17/2012 | GW | 045-14598 | SPECIALTY 14C-21-692 | PR |

General Comment:

Facilities on location ID 335162

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Ancillary equipment # 1

Comment: [Chemical unit at wellhead](#)

Corrective Action:

Date:

corrective date

Type: Plunger Lift # 8

Comment:

Corrective Action:

Date:

Venting:

Yes/No YES

Comment: [Bradenhead valves open](#)

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

| Inspected Facilities | | | | | | | | | |
|-----------------------|--------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 291462 | Type: | WELL | API Number: | 045-14382 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 291479 | Type: | WELL | API Number: | 045-14384 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 291480 | Type: | WELL | API Number: | 045-14385 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 291481 | Type: | WELL | API Number: | 045-14386 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 291482 | Type: | WELL | API Number: | 045-14387 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 291483 | Type: | WELL | API Number: | 045-14388 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 292115 | Type: | WELL | API Number: | 045-14599 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 292116 | Type: | WELL | API Number: | 045-14598 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): NO

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Culverts | Pass | | | |
| Berms | Pass | | | | | |
| | | Sediment Traps | Pass | | | |
| Seeding | Pass | | | | | |
| | | Gravel | Pass | | | |
| Gravel | Pass | | | | | |
| | | Check Dams | Pass | | | |
| | | Rip Rap | Pass | | | |
| Ditches | Pass | | | | | |
| | | Ditches | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 666802620 | INSPECTION APPROVED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3966031 |