

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/03/2016

Submitted Date:

10/03/2016

Document Number:

666802631**FIELD INSPECTION FORM**

Loc ID 335080 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Axelsson, Aaron	970-230-0926	aaxelson@vnrlc.com	<a href="#">Sr. Production Foreman</a>
Ghan, Scott		sghan@vnrlc.com	<a href="#">Sr. EH&amp;S</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282825	WELL	PR	05/19/2006	GW	045-11844	SPECIALTY 41C-28-692	PR
282826	WELL	PR	05/20/2006	GW	045-11843	SPECIALTY 31C-28-692	PR
282827	WELL	PR	05/18/2006	GW	045-11842	SPECIALTY 31A-28-692	PR
282828	WELL	PR	05/18/2006	GW	045-11841	SPECIALTY 41A-28-692	PR

**General Comment:**[Tank battery on location ID 383333](#)

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Horizontal Heated Separator

# 4

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

# 2

Comment: [Chemical units at gas meter run](#)

Corrective Action:

Date:

Type: Plunger Lift

# 4

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

# 2

Comment:

Corrective Action:

Date:

**Venting:**

Yes/No YES

Comment: [Bradenhead valves open](#)

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**Facility ID: 282825 Type: WELL API Number: 045-11844 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 282826 Type: WELL API Number: 045-11843 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Last production numbers posted 7/2016

Corrective Action:

Date: \_\_\_\_\_

Facility ID: 282827 Type: WELL API Number: 045-11842 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 282828 Type: WELL API Number: 045-11841 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Waddles	Pass					
		Rip Rap	Pass			
Berms	Pass					
		Sediment Traps	Pass			
		Gravel	Pass			
Seeding	Pass					
		Culverts	Pass			
		Check Dams	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT