

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/03/2016

Submitted Date:

10/03/2016

Document Number:

666802632

FIELD INSPECTION FORM

Loc ID 383333 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
 Name of Operator: VANGUARD OPERATING LLC
 Address: 5847 SAN FELIPE #3000
 City: HOUSTON State: TX Zip: 77057

Findings:

18 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S
Axelson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
301850	WELL	PR	10/31/2010	GW	045-18309	SPECIALTY 41B-28-692	PR
301851	WELL	PR	09/15/2010	GW	045-18310	SPECIALTY 32A-28-692	PR
301852	WELL	PR	10/15/2010	GW	045-18311	SPECIALTY 31D-28-692	PR
301853	WELL	PR	03/01/2016	GW	045-18312	SPECIALTY 31B-28-692	PR
301854	WELL	PR	10/13/2010	GW	045-18313	SPECIALTY 41D-28-692	PR
301855	WELL	PR	09/22/2010	GW	045-18314	SPECIALTY 32D-28-692	PR
301856	WELL	PR	10/15/2010	GW	045-18315	SPECIALTY 42C-28-692	PR
301857	WELL	PR	10/15/2010	GW	045-18316	SPECIALTY 42D-28-692	PR
301877	WELL	PR	10/13/2010	GW	045-18318	SPECIALTY 42B-28-692	PR
301878	WELL	PR	09/22/2010	GW	045-18319	SPECIALTY 42A-28-692	PR
301879	WELL	PR	09/15/2010	GW	045-18320	SPECIALIST 32B-28-692	PR
301880	WELL	PR	09/22/2010	GW	045-18321	SPECIALTY 32C-28-692	PR

General Comment:

Shared tank battery with location ID 335080

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	AIRS ID 045-1168-001		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Emission Control Device	# 1				
		Comment:			
		Corrective Action:		Date:	
Ancillary equipment	# 3				
		Comment: Chemical units at wellhead			
		Corrective Action:		Date:	
Gas Meter Run	# 1				
		Comment:			
		Corrective Action:		Date:	
Plunger Lift	# 12				
		Comment:			
		Corrective Action:		Date:	
Horizontal Heated Separator	# 13				
		Comment:			
		Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		39.502217,-107.666397
		Comment:			
		Corrective Action:		Date:	

Paint

Condition	Adequate
Other (Content)	<input type="text"/>

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	8	OTHER	STEEL AST		39.502619,-107.665795
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	625
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	YES	
Comment:	Bradenhead valves open	
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	301850	Type:	WELL	API Number:	045-18309	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	301851	Type:	WELL	API Number:	045-18310	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	301852	Type:	WELL	API Number:	045-18311	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	301853	Type:	WELL	API Number:	045-18312	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	301854	Type:	WELL	API Number:	045-18313	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	301855	Type:	WELL	API Number:	045-18314	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	301856	Type:	WELL	API Number:	045-18315	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	301857	Type:	WELL	API Number:	045-18316	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				

Facility ID: <u>301877</u>	Type: <u>WELL</u>	API Number: <u>045-18318</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment:	<u>Plunger lift</u>			
Corrective Action:		Date:		
Facility ID: <u>301878</u>	Type: <u>WELL</u>	API Number: <u>045-18319</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment:	<u>Plunger lift</u>			
Corrective Action:		Date:		
Facility ID: <u>301879</u>	Type: <u>WELL</u>	API Number: <u>045-18320</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment:	<u>Plunger lift</u>			
Corrective Action:		Date:		
Facility ID: <u>301880</u>	Type: <u>WELL</u>	API Number: <u>045-18321</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment:	<u>Plunger lift</u>			
Corrective Action:		Date:		

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass					
Waddles	Pass					
		Gravel	Pass			
Gravel	Pass					
		Sediment Traps	Pass			
		Check Dams	Pass			
		Rip Rap	Pass			
		Ditches	Pass			
		Culverts	Pass			
Berms	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT