

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/06/2016

Submitted Date:

10/07/2016

Document Number:

666802639**FIELD INSPECTION FORM**

Loc ID 334612 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|-------|------------------------------|---------|
| Contact, General | | cogcc.inspections@encana.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 270111 | WELL | PR | 10/09/2008 | GW | 045-09455 | BENZEL 1-16C (P1W) | PR |
| 270112 | WELL | PR | 05/30/2004 | GW | 045-09456 | BENZEL 1-16D (P1W) | PR |
| 270179 | WELL | PR | 10/27/2003 | GW | 045-09484 | SHAEFFER 12-1C (P1W) | PR |
| 270180 | WELL | PR | 05/31/2004 | GW | 045-09485 | SHAEFFER 12-1D (P1W) | PR |
| 271339 | WELL | PR | 05/25/2004 | GW | 045-09867 | BENZEL 1-15C | PR |
| 271340 | WELL | PR | 04/28/2004 | GW | 045-09868 | SHAEFFER 12-2A (P1W) | PR |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | AIRS ID 045-0835-001 | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

| | | | | | |
|----------------|------|--------|--|--|--|
| Spills: | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|-----------------------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Plunger Lift | # 6 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Vertical Heated Separator | # 5 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tanak ID | SE GPS |
|--------------------|---------------------|----------|-----------|----------|--------|
| METHANOL | 1 | 1000 GAL | STEEL AST | | , |
| Comment: | Centralized battery | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | |
|------------------|----------------------|
| Condition | <input type="text"/> |
| Other (Content) | <input type="text"/> |
| Other (Capacity) | <input type="text"/> |
| Other (Type) | <input type="text"/> |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-----------------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Contents | # | Capacity | Type | Tanak ID | SE GPS |
| CONDENSATE | 1 | 500 BBLs | STEEL AST | | 39.468659,-107.719245 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Paint | | | | | |
| Condition | Adequate | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |
| Other (Type) | | | | | |
| Berms | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Venting: | | | | | |
| Yes/No | NO | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Flaring: | | | | | |
| Type | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

| Inspected Facilities | | | | | | | | | |
|-----------------------|--------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 270111 | Type: | WELL | API Number: | 045-09455 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 270112 | Type: | WELL | API Number: | 045-09456 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 270179 | Type: | WELL | API Number: | 045-09484 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 270180 | Type: | WELL | API Number: | 045-09485 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 271339 | Type: | WELL | API Number: | 045-09867 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 271340 | Type: | WELL | API Number: | 045-09868 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

YES

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Culverts | Pass | | | |
| Rip Rap | Pass | | | | | |
| | | Gravel | Pass | | | |
| | | Ditches | Pass | | | |
| Berms | Pass | | | | | |
| Seeding | Pass | | | | | |
| Ditches | Pass | | | | | |
| Gravel | Pass | | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 666802639 | INSPECTION APPROVED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3971000 |