

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/06/2016

Submitted Date:

10/06/2016

Document Number:

673403724**FIELD INSPECTION FORM**

Loc ID 316764 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 6720Name of Operator: BAYLESS PRODUCER LLC* ROBERT LAddress: 621 17TH ST STE 2300City: DENVER State: CO Zip: 80293**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Trujillo, Helen		notices@rlbayless.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232726	WELL	PR	04/14/1997	OW	107-06140	DRY CREEK FEDERAL 1-14	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-276-3887

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Flare pit fenced.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	#		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Flare	# 1		

Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		40.395410,-107.222200
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS
CRUDE OIL	3	300 BBLS	STEEL AST		40.395200,-107.222020
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
--------	----	--	--

Comment:			
Corrective Action:		Date:	
Flaring:			
Type	Pit		
Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: 232726	Type: WELL	API Number: 107-06140	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Pumping.			
Corrective Action:				Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No apparent soil migration; erosion or soil movement.

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT