

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|----------------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|--------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|-----------------------------------|-----|-------|-----------------|
| Type: Horizontal Heated Separator | # 5 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 5 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 3 | | |

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tanak ID | SE GPS |
|--------------------|---|----------|-----------|----------|--------|
| CONDENSATE | 1 | 300 BBLs | STEEL AST | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | | | | |
|------------------|----------|--|--|--|--|
| Condition | Adequate | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |
| Other (Type) | | | | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tanak ID | SE GPS |
|--------------------|---|----------|-----------|----------|--------|
| PRODUCED WATER | 1 | 200 BBLs | STEEL AST | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | | | | |
|------------------|----------|--|--|--|--|
| Condition | Adequate | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |
| Other (Type) | | | | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|---------|--|-------|
| Yes/No | YES | | |
| Comment: | Bradens | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| Inspected Facilities | | | | | | | | | |
|-----------------------|-----------------------|-------|-------------|-------------|------------------|---------|-----------|---------------|-----------|
| Facility ID: | <u>269644</u> | Type: | <u>WELL</u> | API Number: | <u>045-09389</u> | Status: | <u>PR</u> | Insp. Status: | <u>PR</u> |
| Producing Well | | | | | | | | | |
| Comment: | <u>Producing well</u> | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |
| Facility ID: | <u>287806</u> | Type: | <u>WELL</u> | API Number: | <u>045-13078</u> | Status: | <u>PR</u> | Insp. Status: | <u>PR</u> |
| Producing Well | | | | | | | | | |
| Comment: | <u>Producing well</u> | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |
| Facility ID: | <u>287807</u> | Type: | <u>WELL</u> | API Number: | <u>045-13077</u> | Status: | <u>PR</u> | Insp. Status: | <u>PR</u> |
| Producing Well | | | | | | | | | |
| Comment: | <u>Producing well</u> | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |
| Facility ID: | <u>287808</u> | Type: | <u>WELL</u> | API Number: | <u>045-13076</u> | Status: | <u>PR</u> | Insp. Status: | <u>PR</u> |
| Producing Well | | | | | | | | | |
| Comment: | <u>Producing well</u> | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |
| Facility ID: | <u>287809</u> | Type: | <u>WELL</u> | API Number: | <u>045-13075</u> | Status: | <u>PR</u> | Insp. Status: | <u>PR</u> |
| Producing Well | | | | | | | | | |
| Comment: | <u>Producing well</u> | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? P

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? Pass

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | | | | | |
| Seeding | Pass | | | | | |
| | | Ditches | Pass | | | |
| Gravel | Pass | | | | | |
| | | Compaction | Pass | | | |
| | | Culverts | Pass | | | |
| Ditches | Pass | | | | | |
| | | Gravel | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 674703211 | INSPECTION APPROVED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3971705 |