

Location

Overall Good:

| Signs/Marker: | | | |
|----------------------|----------------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|---|-------|-------|
| Emergency Contact Number: | | | |
| Comment: | 970-285-9377 | | |
| Corrective Action: | | Date: | _____ |

Overall Good:

| Spills: | | | |
|----------------|------|--------|--|
| Type | Area | Volume | |
| | | | |

In Containment: No

Comment: _____

Multiple Spills and Releases?

| Fencing/: | | | |
|--------------------|--------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Equipment: | | | corrective date |
|-----------------------------------|-----|-------|-----------------|
| Type: Plunger Lift | # 6 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 6 | | |

| | | | |
|-----------------------|-----|--|-------|
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bird Protectors | # 4 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tanak ID | SE GPS |
|--------------------|---|----------|-----------|----------|--------|
| PRODUCED WATER | 1 | 200 BBLs | STEEL AST | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tanak ID | SE GPS |
|--------------------|---|----------|-----------|----------|--------|
| CONDENSATE | 1 | 300 BBLs | STEEL AST | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|-------|--|
| Yes/No | | |
| Comment: | | |
| Corrective Action: | Date: | |

Flaring:

| | |
|------|--|
| Type | |
|------|--|

| | | |
|--------------------|-------|--|
| Comment: | | |
| Corrective Action: | Date: | |

| |
|--|
| |
|--|

| Inspected Facilities | | | | | | | | | |
|-----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 262908 | Type: | WELL | API Number: | 045-08073 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 262910 | Type: | WELL | API Number: | 045-08075 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 272791 | Type: | WELL | API Number: | 045-10155 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 272792 | Type: | WELL | API Number: | 045-10154 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 285491 | Type: | WELL | API Number: | 045-12509 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 285493 | Type: | WELL | API Number: | 045-12508 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? P

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| | | | | Material Handling And Spill Prevention | Pass | |
| Gravel | Pass | | | | | |
| Seeding | In Process | | | | | |
| | | Gravel | Pass | | | |
| Compaction | Pass | | | | | |
| | | Ditches | Pass | | | |
| Berms | Pass | | | | | |
| Ditches | Pass | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 674703206 | INSPECTION APPROVED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3971700 |