

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Type: Plunger Lift	# 1				
Type: Gas Meter Run	# 1				
Type: Horizontal Heated Separator	# 1				

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS
METHANOL	1	OTHER	STEEL AST		

Comment: Centralized battery

Corrective Action:

Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity) 500gal

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:

Corrective Action:

Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		39.455698,-107.701556

Comment:

Corrective Action:	Date:
--------------------	-------

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO			
Comment:				
Corrective Action:				Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 211189 Type: WELL API Number: 045-06948 Status: PR Insp. Status: PR

Producing Well

Comment: [Plunger lift](#)

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): NO

Comment:

Pilot: Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Seeding	Pass					
		Ditches	Pass			
Gravel	Pass					
		Culverts	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT