

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/11/2016

Submitted Date:

10/11/2016

Document Number:

673403727

FIELD INSPECTION FORM

Loc ID 313198 Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 56565
Name of Operator: MERIT ENERGY COMPANY
Address: 13727 NOEL ROAD STE 1200
City: DALLAS State: TX Zip: 75240

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Jagoda, Kurt		Kurt.Jagoda@meritenergy.com	All Inspections
Valliquette, Arlene		Arlene.Valliquette@meritenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272946	WELL	PR	08/24/2005	GW	081-07190	FEDERAL 34-33	PR

General Comment:

(This area is intentionally left blank for general comments.)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:

Type:		#		corrective date
Bird Protectors				
Comment:				
Corrective Action:			Date:	
Deadman # & Marked		# 4		
Comment:				
Corrective Action:			Date:	
Plunger Lift		# 1		
Comment:				
Corrective Action:			Date:	
Horizontal Heated Separator		# 1		
Comment:				
Corrective Action:			Date:	

Tanks and Berms:					
Contents	#	Capacity	Type	Tanak ID	SE GPS
CRUDE OIL	1	400 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate			Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		40.865240,-107.838230
Comment:					
Corrective Action:					Date:

Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate			Adequate	
Comment:					
Corrective Action:					Date:

Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:

Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 272946 Type: WELL API Number: 081-07190 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT