

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/11/2016

Submitted Date:

10/12/2016

Document Number:

675203392

**FIELD INSPECTION FORM**

Loc ID 312608 Inspector Name: CONKLIN, CURTIS On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 53255  
Name of Operator: MARALEX RESOURCES, INC  
Address: P O BOX 338  
City: IGNACIO State: CO Zip: 81137

**Findings:**

6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Ellsworth, Stuart		Stuart.ellsworth@state.co.us	<a href="#">Engineering Supervisor</a>
Tahmahkera, Kerry	(970) 563-4000	maralextech@gmail.com	<a href="#">All Inspections</a>
O'Hare, Mickey	(970) 563-4000/ (719) 429-3529	amohare@maralexinc.com	<a href="#">All Inspections</a>
Giboo, David	(970) 319-2211	dgiboo@blm.com	<a href="#">Lead Petroleum Engineering Tech</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222010	WELL	SI	06/01/1995	GW	077-08612	SOUTH SHALE RIDGE 3-20	TA

**General Comment:**

[Follow up to inspection Doc#675202732. Correspondence for extension of the expiration of the NOI to plug on file Doc#2597221](#)

**Inspected Facilities**

Facility ID: 222010 Type: WELL API Number: 077-08612 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_