

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/04/2016

Submitted Date:

10/04/2016

Document Number:

674004443

FIELD INSPECTION FORM

Loc ID 332982 Inspector Name: Carlile, Craig On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1625 BROADWAY STE 2200
City: DENVER State: CO Zip: 80202

Findings:

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260681	WELL	PR	09/01/2007	GW	123-20531	BB DRAW H 4-6JI	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	No operator ID at wellhead.		
Corrective Action:	Install appropriate signage at wellhead.	Date:	12/05/2016

Emergency Contact Number:

Comment:	No emergency contact number at well head.		
Corrective Action:	Install appropriate signage at wellhead.	Date:	11/07/2016

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	TANK BATTERY		
Comment:	Barb Wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Pipe		
Corrective Action:		Date:	

Equipment:

Type	#		corrective date
Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	OTHER	PBV CONCRETE		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	<input type="text"/>
-----------	----------------------

Other (Content)	
Other (Capacity) 60 Bbl	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	OTHER	PBV CONCRETE		
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity) 48 Bbl	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Shared with crude oil tanks.				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.257790,-104.667840
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	
Comment:	
Corrective Action:	Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 260681 Type: WELL API Number: 123-20531 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Comment: Bradenhead plumbed to surface.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<u>Routine inspection. Install appropriate signage at well head for operator ID and emergency contact number.</u>	carlilec	10/04/2016