

**Amoco-Federal 21-1**

Inspection# 673403737

Pit adjacent to underground  
tank.



Pit in tank battery.





Stained soil at wellhead.



Stained soil at pump jack exhaust.

