

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/14/2016

Submitted Date:

10/14/2016

Document Number:

684902461**FIELD INSPECTION FORM**

Loc ID 302733 Inspector Name: Pesicka, Conor On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
300384	WELL	PR	09/21/2016	OW	123-29708	LARSEN FAIRMEADOWS 5-30	WK

General Comment:

Inspected FacilitiesFacility ID: 300384 Type: WELL API Number: 123-29708 Status: PR Insp. Status: WK**Cement**Cement ContractorContractor Name: Bayou

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging OperationsDepth Plugs(feet range): 6432, 2724-2462Cement Volume (sx): 2, 122

Good Return During Job: _____

Cement Type: _____

Comment: CIBP @ 6532 w/ 2 sxs cmt on top, pump balance and shoe plug w/ 122 sxs
Change to plugging procedure approved by Mike HickeyCorrective Action:

Date: _____