

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/14/2016

Submitted Date:

10/14/2016

Document Number:

684902462**FIELD INSPECTION FORM**

Loc ID 302732 Inspector Name: Pesicka, Conor On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
300383	WELL	PR	09/21/2016	OW	123-29707	Larson Fairmeadows 6-30	WK

**General Comment:**

**Inspected Facilities**Facility ID: 300383 Type: WELL API Number: 123-29707 Status: PR Insp. Status: WK**Cement**Cement ContractorContractor Name: Leed

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging OperationsDepth Plugs(feet range): 6434', 2508', 885'Cement Volume (sx): 10, 20, 71Good Return During Job: YES

Cement Type: \_\_\_\_\_

Comment: CIBP @ 6434' w/ 10 sxs, bal @ 2508' w/ 20 sxs, plug @ 885' w/ 71 sxs to surf rd

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_