

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/17/2016

Submitted Date:

10/17/2016

Document Number:

673403754

**FIELD INSPECTION FORM**

Loc ID 313040 Inspector Name: Waldron, Emily On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 6975  
 Name of Operator: BEARTOOTH OIL & GAS COMPANY  
 Address: P O BOX 398  
 City: FRUITA State: CO Zip: 81521-

**Findings:**

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
currey, ken	(970) 858-4158	bogcken@180com.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223426	WELL	PR	11/10/1995	GW	081-06792	FEDERAL SANDWASH 2-1	PR

**General Comment:**

*(This area is intentionally left blank for general comments.)*

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#		corrective date
Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Bird Protectors	#		
Comment:			
Corrective Action:		Date:	
Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		40.686260,-107.550200
Comment:					
Corrective Action:				Date:	

<b>Paint</b>	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	200 BBLs	PBV STEEL		40.686690,-107.549690
Comment:					
Corrective Action:					Date:

<b>Paint</b>	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>	
Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 223426 Type: WELL API Number: 081-06792 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT