

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/18/2016

Submitted Date:

10/18/2016

Document Number:

673403758**FIELD INSPECTION FORM**
 Loc ID 313167 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10548Name of Operator: HRM RESOURCES II LLCAddress: 410 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Pape, Terry	970-768-5700	tpape@hrmres.com	All Inspections
Prohaska, April	303-893-6621	aprohaska@hrmres.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267927	WELL	PR	05/15/2003	GW	081-07131	SCHROEDER 33-32	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 720-830-6046

Corrective Action:

Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pig Station	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	#		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		

Comment:			
Corrective Action:		Date:	
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS	
PRODUCED WATER	1	400 BBLs	HEATED STEEL AST		40.780780,-107.855510	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				

Contents	#	Capacity	Type	Tanak ID	SE GPS	
CONDENSATE	1	400 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			

Flaring:

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	267927	Type:	WELL	API Number:	081-07131	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No apparent soil migration; erosion or soil movement.

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT