



photo 1: Facing northeast toward the location from the access road.



photo 2: Facing northeast toward the location.



photo 3: Facing southeast toward the location.



photo 4: North side of the location facing south.



photo 5: South of the location facing east off the access road. This area has no crop establishment.



photo 6: Facing west toward the surrounding crop cover.