

Location

Lease Road:

Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	1	500 BBLs	STEEL AST		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:		
Corrective Action:		Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--

Inspected Facilities

Facility ID: 273305 Type: WELL API Number: 077-08812 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass			
Compaction	Pass	Gravel	Pass			
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT