

API # 001-08804, DEBRIS ON WELL SITE.



BRADENHEAD IS NOT PLUMED TO SURFACE, STAINED SOIL AT WELLHEAD.



DEBRIS AT SEPARATOR



DEBRIS AT TANK BATTERY

