

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/21/2016

Submitted Date:

10/24/2016

Document Number:

666802659**FIELD INSPECTION FORM**

Loc ID 334631 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Findings:**9 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273995	WELL	PR	05/22/2009	GW	045-10309	HMU 16-2 (B16W)	PR
276639	WELL	PR	12/25/2008	GW	045-10500	HMU 9-15C (B16W)	PR
276643	WELL	PR	01/01/2009	GW	045-10501	HMU 16-2C (B16W)	PR
276644	WELL	PR	01/05/2009	GW	045-10502	HMU 16-7(B16W)	PR
276645	WELL	PR	01/10/2009	GW	045-10503	HMU 16-6 (B16W)	PR
295826	WELL	PR	12/25/2008	GW	045-15819	ROSE RANCH 16-1C (B16W)	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	AIRS ID 045-0959-001		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Gas Meter Run	# 1				
Ancillary equipment	# 1	Blow down tank			
Plunger Lift	# 6				
Horizontal Heated Separator	# 6				
Emission Control Device	# 1				

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		
Comment:	Centralized battery				
Corrective Action:				Date:	

Paint

Condition Adequate

Other (Content)

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	4	OTHER	STEEL AST		39.450637,-107.777780
Comment:					
Corrective Action:					
					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	250bbbs	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
			Date:

Flaring:

Type	
Comment:	
Corrective Action:	
	Date:

Inspected Facilities									
Facility ID:	<u>273995</u>	Type:	<u>WELL</u>	API Number:	<u>045-10309</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>276639</u>	Type:	<u>WELL</u>	API Number:	<u>045-10500</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>276643</u>	Type:	<u>WELL</u>	API Number:	<u>045-10501</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>276644</u>	Type:	<u>WELL</u>	API Number:	<u>045-10502</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>276645</u>	Type:	<u>WELL</u>	API Number:	<u>045-10503</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>295826</u>	Type:	<u>WELL</u>	API Number:	<u>045-15819</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>								
Corrective Action:					Date:				

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Retention Ponds	Pass					
Berms	Pass					
Seeding	Pass					
		Culverts	Pass			
		Gravel	Pass			
Gravel	Pass					
		Ditches	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT