

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/24/2016

Submitted Date:

10/24/2016

Document Number:

684902471**FIELD INSPECTION FORM**

Loc ID 309933 Inspector Name: Pesicka, Conor On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275023	WELL	PR	12/06/2004	GW	123-25612	BRANDT 43-13	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	agricultural		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		

Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		40.049060,-104.720480	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	PBV CONCRETE		40.049060,-104.720480	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	60bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shared with crude oil				
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:	Date:		

**Flaring:**

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	275023	Type:	WELL	API Number:	123-25612	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR							
Corrective Action:						Date:			
BradenHead									
Comment:		Bradenhead plumbed to surface							
Corrective Action:						Date:			

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	<div></div> <div>Date: </div>
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT