

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/24/2016

Submitted Date:

10/24/2016

Document Number:

673403791**FIELD INSPECTION FORM**
 Loc ID 313204 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 56565Name of Operator: MERIT ENERGY COMPANYAddress: 13727 NOEL ROAD STE 1200City: DALLAS State: TX Zip: 75240**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name        | Phone | Email                              | Comment                         |
|---------------------|-------|------------------------------------|---------------------------------|
| Valliquette, Arlene |       | Arlene.Valliquette@meritenergy.com | <a href="#">All Inspections</a> |
| Jagoda, Kurt        |       | Kurt.Jagoda@meritenergy.com        | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 273275      | WELL | PR     | 04/17/2015  | GW         | 081-07197 | FEDERAL 43-20 | PR          |

**General Comment:**

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | CONTAINERS           |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment: 307-783-2627

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |              |       |  |
|--------------------|--------------|-------|--|
| <b>Fencing/:</b>   |              |       |  |
| Type               | TANK BATTERY |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |
| Type               | SEPARATOR    |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |

|                          |     |       |                 |
|--------------------------|-----|-------|-----------------|
| <b>Equipment:</b>        |     |       | corrective date |
| Type: Gas Meter Run      | # 1 |       |                 |
| Comment:                 |     |       |                 |
| Corrective Action:       |     | Date: |                 |
| Type: Bird Protectors    | #   |       |                 |
| Comment:                 |     |       |                 |
| Corrective Action:       |     | Date: |                 |
| Type: Deadman # & Marked | # 4 |       |                 |

|                                   |     |       |  |
|-----------------------------------|-----|-------|--|
| Comment:                          |     |       |  |
| Corrective Action:                |     | Date: |  |
| Type: Horizontal Heated Separator | # 1 |       |  |
| Comment:                          |     |       |  |
| Corrective Action:                |     | Date: |  |
| Type: Plunger Lift                | # 1 |       |  |
| Comment:                          |     |       |  |
| Corrective Action:                |     | Date: |  |

**Tanks and Berms:**

|                    |   |          |           |          |                       |       |
|--------------------|---|----------|-----------|----------|-----------------------|-------|
| Contents           | # | Capacity | Type      | Tanak ID | SE GPS                |       |
| PRODUCED WATER     | 1 | 400 BBLS | STEEL AST |          | 40.895620,-107.851030 |       |
| Comment:           |   |          |           |          |                       |       |
| Corrective Action: |   |          |           |          |                       | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth              | Adequate |                     |                     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     |             |

|                    |   |          |           |          |        |       |
|--------------------|---|----------|-----------|----------|--------|-------|
| Contents           | # | Capacity | Type      | Tanak ID | SE GPS |       |
| CRUDE OIL          | 1 | 400 BBLS | STEEL AST |          | ,      |       |
| Comment:           |   |          |           |          |        |       |
| Corrective Action: |   |          |           |          |        | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth              | Adequate |                     |                     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     |             |

**Venting:**

|        |    |  |  |
|--------|----|--|--|
| Yes/No | NO |  |  |
|--------|----|--|--|

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

|                             |            |                       |            |                  |
|-----------------------------|------------|-----------------------|------------|------------------|
| <b>Inspected Facilities</b> |            |                       |            |                  |
| Facility ID: 273275         | Type: WELL | API Number: 081-07197 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b>       |            |                       |            |                  |
| Comment:                    |            |                       |            |                  |
| Corrective Action:          |            |                       |            | Date:            |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: No apparent soil migration; erosion or soil movement.

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT