

Final Reclamation Inspection- Overview



Aerial photo taken 2015 using COGCC GISOnline database. 123-12443 was reclaimed in 2007 but two additional locations (123-26059 and 123-25285) were added later in 2007. Therefore, disturbances due to the other locations will result in a well release on active locations.

Final Reclamation Inspection



Photo 1. Photo taken from center of location, facing West. Access road to Producing location 123-26059.

Final Reclamation Inspection



Photo 2. Photo taken from center of location, facing North. Location on the western edge of an active tank battery location.

Final Reclamation Inspection



Photo 3. Photo taken from center of location, facing East. Location on the western edge of an active tank battery location.