

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
10/26/2016  
Submitted Date:  
10/26/2016  
Document Number:  
681901625

**FIELD INSPECTION FORM**

Loc ID 336399 Inspector Name: HELGELAND, GARY On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**  
OGCC Operator Number: 10633  
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC  
Address: 370 17TH STREET #2170  
City: DENVER State: CO Zip: 80202

**Findings:**  
22 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		Cogcc.inspections@crestone pr.com	<b>ALL INSPECTIONS</b>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241227	WELL	PR	03/29/1977	GW	123-09015	HALEY 1	PR
301054	WELL	PR	01/26/2009	OW	123-29898	HALEY 31-22	PR
301055	WELL	PR	01/26/2009	GW	123-29899	HALEY 8-2-22	PR
301056	WELL	PR	03/06/2010	GW	123-29900	HALEY 8-4-22	PR
301057	WELL	PR	03/17/2010	GW	123-29901	HALEY 4-2-22	PR

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	SATISFACTORY		
Corrective Action:			Date:
Type	BATTERY		
Comment:	SATISFACTORY		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	SATISFACTORY		
Corrective Action:			Date:

Emergency Contact Number:

Comment: SATISFACTORY

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	SATISFACTORY		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	SATISFACTORY		
Corrective Action:			Date:

**Equipment:**

Type			corrective date
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:	SATISFACTORY		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 5		
Comment:	SATISFACTORY		
Corrective Action:			Date:
Type: Bird Protectors	# 6		

Comment: SATISFACTORY		Date:
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment: SATISFACTORY		Date:
Corrective Action:		Date:
Type: Gas Meter Run	# 2	
Comment: SATISFACTORY		Date:
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tanak ID	SE GPS
CRUDE OIL	3	300 BBLs	STEEL AST		40.126204,-104.984269
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:		Date:		

**Venting:**

Yes/No	NO	
--------	----	--

Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	241227	Type:	WELL	API Number:	123-09015	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR							Date:	
Corrective Action:								Date:	
<b>BradenHead</b>									
Comment:	Bradenhead is plumed to surface.							Date:	
Corrective Action:								Date:	
Facility ID:	301054	Type:	WELL	API Number:	123-29898	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR							Date:	
Corrective Action:								Date:	
<b>BradenHead</b>									
Comment:	Bradenhead is plumed to surface.							Date:	
Corrective Action:								Date:	
Facility ID:	301055	Type:	WELL	API Number:	123-29899	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR							Date:	
Corrective Action:								Date:	
<b>BradenHead</b>									
Comment:	Bradenhead is plumed to surface.							Date:	
Corrective Action:								Date:	
Facility ID:	301056	Type:	WELL	API Number:	123-29900	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR							Date:	
Corrective Action:								Date:	
<b>BradenHead</b>									
Comment:	Bradenhead is plumed to surface.							Date:	
Corrective Action:								Date:	
Facility ID:	301057	Type:	WELL	API Number:	123-29901	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR							Date:	
Corrective Action:								Date:	

**BradenHead**

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Environmental**

**Spill/Remediation:**

Comment:

Corrective  
Action:

Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? Pass Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation In

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Overall Interim Reclamation In Process

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT