

All Photos were taken on 10/25/2016



Former sample location, "5". Note fill soil on right of picture.





Crews working the fill material into pit excavation.





Soil pile in the foreground, is contaminated material that needs to be hauled off to offsite disposal







Pushing fill material into pit.



Soil pile in the foreground, is contaminated material that needs to be hauled off to offsite disposal



Soil pushed into excavation, note marker in foreground is former sample location "5"



Crew picking up small pieces of trash.



Material spread on location to assess if it has been contaminated with any foreign material.



Material spread on location to assess if it has been contaminated with any foreign material.



Material spread on location to assess if it has been contaminated with any foreign material.



Material spread on location to assess if it has been contaminated with any foreign material.



Photo of fill material, looking south.



Material spread on location to assess if it has been contaminated with any foreign material. , looking east



Material spread on location to assess if it has been contaminated with any foreign material.





Fill material



Fill material



Fill material



Fill material



Material spread on location to assess if it has been contaminated with any foreign material.



Material spread on location to assess if it has been contaminated with any foreign material.



Foreign material in fill.



Material spread on location to assess if it has been contaminated with any foreign material.



Material spread on location to assess if it has been contaminated with any foreign material.



Material spread on location to assess if it has been contaminated with any foreign material.



Material spread on location to assess if it has been contaminated with any foreign material.