

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
10/27/2016
Submitted Date:
10/27/2016
Document Number:
674703274

FIELD INSPECTION FORM

Loc ID 335729 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 53650
Name of Operator: MARATHON OIL COMPANY
Address: 1501 STAMPEDE AVENUE
City: CODY State: WY Zip: 82414

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Stebbins, Tiffany	307-527-2223	tastebbins@marathonoil.com	Regulatory Compli Rep (Wyoming)

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292469	WELL	PR	04/04/2009	GW	045-14728	697-12A 12	PR
293509	WELL	PR	02/28/2009	GW	045-15020	697-12A 25	PR
293510	WELL	PR	05/25/2009	GW	045-15021	697-12A 27	PR
293530	WELL	PR	02/28/2009	GW	045-15034	697-12A 16	PR
293531	WELL	PR	05/14/2010	GW	045-15035	697-12A 14	PR
293532	WELL	PR	04/01/2009	GW	045-15036	697-12A 21	PR
293533	WELL	PR	04/01/2009	GW	045-15037	697-12A 23	PR
299531	WELL	PR	04/01/2009	GW	045-17701	697-12A 14B	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Bird Protectors	# 4		corrective date
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		,

Comment:	
Corrective Action:	Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	
Corrective Action:	Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	2	400 BBLs	STEEL AST		,

Comment:	
Corrective Action:	Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	
Corrective Action:	Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	292469	Type:	WELL	API Number:	045-14728	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	293509	Type:	WELL	API Number:	045-15020	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	293510	Type:	WELL	API Number:	045-15021	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	293530	Type:	WELL	API Number:	045-15034	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	293531	Type:	WELL	API Number:	045-15035	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	293532	Type:	WELL	API Number:	045-15036	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	293533	Type:	WELL	API Number:	045-15037	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	299531	Type:	WELL	API Number:	045-17701	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				

--

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
Gravel	Pass					
Seeding	Pass					
Berms	Pass					
		Culverts	Pass			
Compaction	Pass					
		Ditches	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT