



photo 1: Facing south toward the location.



photo 2: Well sign. The emergency number is disconnected.



photo 3: There are noxious weeds (Bull thistle) growing at the pit.



photo 4: Facing north along the fill slope.