

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/28/2016

Submitted Date:

10/31/2016

Document Number:

666802685**FIELD INSPECTION FORM**
 Loc ID 335277 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Axelsson, Aaron	970-230-0926	aaxelson@vnrlc.com	<a href="#">Sr. Production Foreman</a>
Ghan, Scott		sghan@vnrlc.com	<a href="#">Sr. EH&amp;S</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211446	WELL	PR	05/20/2015	GW	045-07206	GIBSON GULCH UNIT 13-30	PR
268445	WELL	PR	09/06/2003	GW	045-09259	GIBSON GLCH UNIT 12-30	PR
270374	WELL	PR	04/26/2005	GW	045-09540	GIBSON GULCH UNIT 12-30 D	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

# 3

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

# 0

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

# 2

Comment:

Corrective Action:

Date:

Type: Vertical Heated Separator

# 0

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

# 2

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	1	200 BBLs	STEEL AST		,

Comment: Centralized battery

Corrective Action:

Date:

**Paint**

Condition

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tanak ID	SE GPS		
CONDENSATE	1	300 BBLs	STEEL AST		39.492906,-107.603469		
Comment:							
Corrective Action:						Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:		Date:		

**Venting:**

Yes/No	YES	
Comment:	Bradenhead valves open	
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities			
Facility ID: 211446	Type: WELL	API Number: 045-07206	Status: PR    Insp. Status: PR
<b>Producing Well</b>			
Comment:	Plunger Lift		
Corrective Action:		Date:	
Facility ID: 268445	Type: WELL	API Number: 045-09259	Status: PR    Insp. Status: PR
<b>Producing Well</b>			
Comment:	Plunger Lift		
Corrective Action:		Date:	
Facility ID: 270374	Type: WELL	API Number: 045-09540	Status: PR    Insp. Status: PR
<b>Producing Well</b>			
Comment:	Plunger Lift		
Corrective Action:		Date:	

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	<div></div> <div>Date: </div>
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Check Dams	Pass			
		Ditches	Pass			
Seeding	Pass					
Gravel	Pass					
		Culverts	Pass			
		Gravel	Pass			
Ditches	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT