

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/28/2016

Submitted Date:

10/31/2016

Document Number:

666802686**FIELD INSPECTION FORM**

Loc ID 323980 Inspector Name: Murray, Richard On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10531  
 Name of Operator: VANGUARD OPERATING LLC  
 Address: 5847 SAN FELIPE #3000  
 City: HOUSTON State: TX Zip: 77057

**Findings:**

- 6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, Aaron	970-230-0926	aaxelson@vnrlc.com	<a href="#">Sr. Production Foreman</a>
Ghan, Scott		sghan@vnrlc.com	<a href="#">Sr. EH&amp;S</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211400	WELL	PR	06/12/1997	GW	045-07160	GIBSON GULCH UNIT 15-30	PR

**General Comment:**

[Shared facilities with location ID 324013](#)

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#	Comment	Corrective Action	Date	corrective date
Type: Plunger Lift	# 1				
Type: Gas Meter Run	# 2				
Type: Horizontal Heated Separator	# 2				

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	1	200 BBLs	STEEL AST		39.493723,-107.595794

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	1	100 BBLs	PBV STEEL		

Comment: [Centralized battery](#)

Corrective Action:	Date:
--------------------	-------

**Paint**

Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	YES	Date:	
Comment:	Bradenhead valve open		
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 211400 Type: WELL API Number: 045-07160 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Plunger Lift](#)

Corrective Action:

Date:

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:  Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Seeding	Pass					
		Culverts	Pass			
Gravel	Pass					
		Ditches	Pass			
Ditches	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT