

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/31/2016

Submitted Date:

10/31/2016

Document Number:

666802688**FIELD INSPECTION FORM**
 Loc ID 324013 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Axelsson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211490	WELL	PR	09/01/2004	GW	045-07250	GIBSON GULCH UNIT 10-30 D	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS
METHANOL	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity) 500gal

Other (Type)

Berms

Type	Capacity		Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:							
Corrective Action:						Date:	
Contents		#	Capacity	Type	Tanak ID	SE GPS	
CONDENSATE		1	200 BBLS	STEEL AST		39.495341,-107.593397	
Comment:							

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	1	<100 BBLs	PBV STEEL		,
Comment:	Centralized battery				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	YES		
Comment:	Bradenhead valve open		
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	211490	Type:	WELL	API Number:	045-07250	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger Lift								
Corrective Action:						Date:			

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	<div></div> <div>Date: </div>
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
		Ditches	Pass			
		Culverts	Pass			
Seeding	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT