

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/27/2016

Submitted Date:

10/27/2016

Document Number:

675203516**FIELD INSPECTION FORM**

Loc ID 334733	Inspector Name: CONKLIN, CURTIS	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> <div style="border: 1px solid black; padding: 2px;"> 4    Number of Comments  0    Number of Corrective Actions  <input type="checkbox"/> Corrective Action Response Requested </div>
------------------	------------------------------------	---	-------------------	--

**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Contact Information:**

Contact Name	Phone	Email	Comment
Encana,		cogcc.inspections@encana.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290040	WELL	PR	08/10/2012	GW	045-13964	MAP LLC 11-11(PK11)	SI
290041	WELL	PR	04/20/2008	GW	045-13963	MAP LLC 11-12 (PK11)	SI
290042	WELL	PR	11/01/2012	GW	045-13962	MAP LLC 11-13 (PK11)	PR
290043	WELL	PR	04/19/2008	GW	045-13961	MAP LLC 11-14 (PK11)	PR
292399	WELL	PR	04/20/2008	GW	045-14721	MAP LLC 11-11BB (PK11)	PR
292400	WELL	PR	10/01/2012	GW	045-14720	MAP LLC 11-13BB (PK11)	PR
292488	WELL	PR	06/01/2013	GW	045-14729	MAP LLC 11-12BB (PK11)	SI
293124	WELL	PR	10/25/2007	GW	045-14899	MAP LLC 11-14BB (PK11)	PR

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Flare	# 1		
Comment:	Connected to 045-13963 and 045-14729. Ensure that flaring is in compliance with Rule 912.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	4	300 BBLS	STEEL AST		,

Comment:		
Corrective Action:		Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 290040 Type: WELL API Number: 045-13964 Status: PR Insp. Status: SIFacility ID: 290041 Type: WELL API Number: 045-13963 Status: PR Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: flare on bradenhead

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 290042 Type: WELL API Number: 045-13962 Status: PR Insp. Status: PRFacility ID: 290043 Type: WELL API Number: 045-13961 Status: PR Insp. Status: PRFacility ID: 292399 Type: WELL API Number: 045-14721 Status: PR Insp. Status: PRFacility ID: 292400 Type: WELL API Number: 045-14720 Status: PR Insp. Status: PRFacility ID: 292488 Type: WELL API Number: 045-14729 Status: PR Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: flare on bradenhead

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 293124 Type: WELL API Number: 045-14899 Status: PR Insp. Status: PR

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Ditches	Pass					
Retention Ponds	Pass					
Berms	Pass	Compaction	Pass			
Compaction	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675203516	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3986386">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3986386</a>