

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/28/2016

Submitted Date:

10/28/2016

Document Number:

675203521**FIELD INSPECTION FORM**

Loc ID 334453	Inspector Name: CONKLIN, CURTIS	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>10433</u> Name of Operator: <u>LARAMIE ENERGY LLC</u> Address: <u>1401 SEVENTEENTH STREET #1400</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				Findings: 1 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Bankert, Wayne	(970) 683-5419	wbankert@laramie-energy.com	Senior Regulatory & Environmental Coordinator

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290703	WELL	PR	05/23/2007	GW	077-09298	VEGA UNIT 10-334	PR
290704	WELL	PR	05/23/2007	GW	077-09297	VEGA UNIT 10-234	PR
290705	WELL	PR	05/23/2007	GW	077-09296	VEGA UNIT 10-434	PR
290706	WELL	PR	05/23/2007	GW	077-09295	VEGA UNIT 10-431	PR
292279	WELL	PR	09/17/2007	GW	077-09391	VEGA FEDERAL 10-344	PR
292280	WELL	PR	09/17/2007	GW	077-09390	VEGA FEDERAL 10-241	PR
292281	WELL	PR	09/17/2007	GW	077-09389	VEGA FEDERAL 10-444	PR
292282	WELL	PR	09/23/2009	GW	077-09388	VEGA FEDERAL 10-441	PR
292283	WELL	PR	09/17/2007	GW	077-09387	VEGA FEDERAL 10-341	PR
292284	WELL	PR	09/17/2007	GW	077-09386	VEGA FEDERAL 10-244	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	1	400 BBLS	HEATED STEEL AST		,
Comment: <input type="text"/>					
Corrective Action: <input type="text"/>					Date: <input type="text"/>

Paint

Condition	Adequate
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: <input type="text"/>				
Corrective Action: <input type="text"/>				Date: <input type="text"/>

Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	1	400 BBLS	STEEL AST		,
Comment: <input type="text"/>					
Corrective Action: <input type="text"/>					Date: <input type="text"/>

Paint

Condition	Adequate
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment: <input type="text"/>				

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tanak ID	SE GPS	
METHANOL	1	<50 BBLS	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>290703</u>	Type:	<u>WELL</u>	API Number:	<u>077-09298</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>290704</u>	Type:	<u>WELL</u>	API Number:	<u>077-09297</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>290705</u>	Type:	<u>WELL</u>	API Number:	<u>077-09296</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>290706</u>	Type:	<u>WELL</u>	API Number:	<u>077-09295</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>292279</u>	Type:	<u>WELL</u>	API Number:	<u>077-09391</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>292280</u>	Type:	<u>WELL</u>	API Number:	<u>077-09390</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>292281</u>	Type:	<u>WELL</u>	API Number:	<u>077-09389</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>292282</u>	Type:	<u>WELL</u>	API Number:	<u>077-09388</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>292283</u>	Type:	<u>WELL</u>	API Number:	<u>077-09387</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>292284</u>	Type:	<u>WELL</u>	API Number:	<u>077-09386</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Compaction	Pass	Gravel	Pass			
Gravel	Pass					
Berms	Pass	Compaction	Pass			
Rip Rap	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675203521	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3987732