

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/03/2016

Submitted Date:

11/04/2016

Document Number:

675203539**FIELD INSPECTION FORM**
 Loc ID 336045 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 6301 DEAUVILLE BLVDCity: MIDLAND State: TX Zip: 79706**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Justus, Julie	(970) 257-6042	jjustus@chevron.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290195	WELL	PR	09/27/2008	GW	045-14036	SKR 598-35-AV-06	PR
291484	WELL	PR	02/03/2008	GW	045-14389	SKR 598-35-AV-13	PR
291485	WELL	PR	05/22/2012	GW	045-14390	SKR 598-35-AV-11	PR
291487	WELL	PR	10/30/2008	GW	045-14392	SKR 598-35-AV-14	PR
291488	WELL	PR	04/30/2009	GW	045-14393	SKR 598-35-AV-18	PR
291489	WELL	PR	02/29/2008	GW	045-14394	SKR 598-35-AV-02	PR
291490	WELL	PR	10/03/2008	GW	045-14395	SKR 598-35-AV-08	PR
291491	WELL	PR	07/20/2007	GW	045-14396	SKR 598-35-AV-15	PR
291492	WELL	PR	06/22/2009	GW	045-14397	SKR 598-35-AV-17	PR
291494	WELL	PR	05/08/2009	GW	045-14400	SKR 598-35-AV-09	PR
291495	WELL	PR	02/14/2008	GW	045-14401	SKR 598-35-AV-03	PR
291496	WELL	PR	02/22/2008	GW	045-14402	SKR 598-35-AV-01	PR
291497	WELL	SI	07/07/2015	GW	045-14403	SKR 598-35-AV-05	SI
291498	WELL	PR	05/15/2009	GW	045-14404	SKR 598-35-AV-07	PR
291499	WELL	PR	11/07/2008	GW	045-14405	SKR 598-35-AV-04	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	400 BBLS	STEEL AST		,
Comment: <input type="text"/>					
Corrective Action: <input type="text"/>					Date: <input type="text"/>

Paint

Condition	Adequate
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: <input type="text"/>				
Corrective Action: <input type="text"/>				Date: <input type="text"/>

Venting:

Yes/No	NO
Comment:	<input type="text"/>
Corrective Action:	Date: <input type="text"/>

Flaring:

Type	<input type="text"/>
Comment:	<input type="text"/>
Corrective Action:	Date: <input type="text"/>

Inspected Facilities				
Facility ID:	<u>290195</u>	Type:	<u>WELL</u>	API Number: <u>045-14036</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>291484</u>	Type:	<u>WELL</u>	API Number: <u>045-14389</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>291485</u>	Type:	<u>WELL</u>	API Number: <u>045-14390</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>291487</u>	Type:	<u>WELL</u>	API Number: <u>045-14392</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>291488</u>	Type:	<u>WELL</u>	API Number: <u>045-14393</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>291489</u>	Type:	<u>WELL</u>	API Number: <u>045-14394</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>291490</u>	Type:	<u>WELL</u>	API Number: <u>045-14395</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>291491</u>	Type:	<u>WELL</u>	API Number: <u>045-14396</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>291492</u>	Type:	<u>WELL</u>	API Number: <u>045-14397</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>291494</u>	Type:	<u>WELL</u>	API Number: <u>045-14400</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>291495</u>	Type:	<u>WELL</u>	API Number: <u>045-14401</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>291496</u>	Type:	<u>WELL</u>	API Number: <u>045-14402</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>291497</u>	Type:	<u>WELL</u>	API Number: <u>045-14403</u> Status: <u>SI</u> Insp. Status: <u>SI</u>
Facility ID:	<u>291498</u>	Type:	<u>WELL</u>	API Number: <u>045-14404</u> Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>291499</u>	Type:	<u>WELL</u>	API Number: <u>045-14405</u> Status: <u>PR</u> Insp. Status: <u>PR</u>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Berms	Pass	Compaction	Pass			
Rip Rap	Pass					
Compaction	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT