

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/03/2016

Submitted Date:

11/03/2016

Document Number:

675203541**FIELD INSPECTION FORM**

Loc ID 336049	Inspector Name: CONKLIN, CURTIS	On-Site Inspection <input type="checkbox"/>	Status Summary:
2A Doc Num: _____			<input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b>  OGCC Operator Number: <u>16700</u>  Name of Operator: <u>CHEVRON USA INC</u>  Address: <u>6301 DEAUVILLE BLVD</u>  City: <u>MIDLAND</u> State: <u>TX</u> Zip: <u>79706</u>			<b>Findings:</b>  1 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Justus, Julie	(970) 257-6042	jjustus@chevron.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296407	WELL	PR	09/03/2011	GW	045-16004	SKR 698-04-AV-01	PR
298457	WELL	PR	11/07/2011	GW	045-17211	SKR 698-04-AV-09	PR
298458	WELL	PR	09/24/2011	GW	045-17212	SKR 698-04-AV-08	PR
298459	WELL	PR	08/13/2010	GW	045-17213	SKR 698-04-AV-07	PR
298460	WELL	PR	09/02/2011	GW	045-17214	SKR-698-04-AV 05	PR
298461	WELL	PR	06/01/2012	GW	045-17215	SKR 698-04-AV-10	PR
298462	WELL	PR	11/03/2011	GW	045-17216	SKR 698-04-AV-13	PR
298463	WELL	PR	10/06/2011	GW	045-17217	SKR 698-04-AV-14	PR
298464	WELL	PR	10/28/2011	GW	045-17218	SKR 698-04-AV-15	PR
298465	WELL	PR	10/08/2011	GW	045-17219	SKR 698-04-AV-16	PR
298466	WELL	PR	10/25/2011	GW	045-17220	SKR 698-04-AV-17	PR
298467	WELL	PR	10/10/2011	GW	045-17221	SKR 698-04-AV-18	PR
298468	WELL	PR	10/23/2011	GW	045-17222	SKR 698-04-AV-19	PR
298470	WELL	PR	10/12/2011	GW	045-17223	SKR 698-04-AV-20	PR
298471	WELL	PR	09/23/2011	GW	045-17224	SKR 698-04-AV-06	PR
298472	WELL	PR	10/21/2011	GW	045-17225	SKR 698-04-AV-21	PR
298473	WELL	PR	10/14/2011	GW	045-17226	SKR 698-04-AV-22	PR
298474	WELL	PR	09/09/2011	GW	045-17227	SKR 698-04-AV-02	PR
298475	WELL	PR	11/05/2011	GW	045-17228	SKR 698-04-AV-11	PR
298476	WELL	PR	06/01/2012	GW	045-17229	SKR 698-04-AV-04	PR
298477	WELL	PR	09/02/2011	GW	045-17230	SKR 698-04-AV-03	PR
298993	WELL	PR	09/30/2011	GW	045-17516	SKR 698-04-AV-12	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type
Comment:
Corrective Action:
Date:

Inspected Facilities				
Facility ID: <u>298407</u>	Type: <u>WELL</u>	API Number: <u>045-16004</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298457</u>	Type: <u>WELL</u>	API Number: <u>045-17211</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298458</u>	Type: <u>WELL</u>	API Number: <u>045-17212</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298459</u>	Type: <u>WELL</u>	API Number: <u>045-17213</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298460</u>	Type: <u>WELL</u>	API Number: <u>045-17214</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298461</u>	Type: <u>WELL</u>	API Number: <u>045-17215</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298462</u>	Type: <u>WELL</u>	API Number: <u>045-17216</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298463</u>	Type: <u>WELL</u>	API Number: <u>045-17217</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298464</u>	Type: <u>WELL</u>	API Number: <u>045-17218</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298465</u>	Type: <u>WELL</u>	API Number: <u>045-17219</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298466</u>	Type: <u>WELL</u>	API Number: <u>045-17220</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298467</u>	Type: <u>WELL</u>	API Number: <u>045-17221</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298468</u>	Type: <u>WELL</u>	API Number: <u>045-17222</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298470</u>	Type: <u>WELL</u>	API Number: <u>045-17223</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298471</u>	Type: <u>WELL</u>	API Number: <u>045-17224</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298472</u>	Type: <u>WELL</u>	API Number: <u>045-17225</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298473</u>	Type: <u>WELL</u>	API Number: <u>045-17226</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298474</u>	Type: <u>WELL</u>	API Number: <u>045-17227</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298475</u>	Type: <u>WELL</u>	API Number: <u>045-17228</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Inspector Name: CONKLIN, CURTIS

Facility ID:	298476	Type:	WELL	API Number:	045-17229	Status:	PR	Insp. Status:	PR
Facility ID:	298477	Type:	WELL	API Number:	045-17230	Status:	PR	Insp. Status:	PR
Facility ID:	298993	Type:	WELL	API Number:	045-17516	Status:	PR	Insp. Status:	PR

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Berms	Pass	Gravel	Pass			
Rip Rap	Pass					
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT