

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/04/2016

Submitted Date:

11/04/2016

Document Number:

675203561**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 324266 CONKLIN, CURTIS 2A Doc Num: _____

Operator Information:OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 6301 DEAUVILLE BLVDCity: MIDLAND State: TX Zip: 79706**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Justus, Julie	(970) 257-6042	jjustus@chevron.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271038	WELL	PR	02/01/2011	GW	045-09796	SKINNER RIDGE 698-28 1	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume			
------	------	--------	--	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS	
PRODUCED WATER	1	400 BBLs	STEEL AST		,	
Comment:	<input type="text"/>					
Corrective Action:	<input type="text"/>				Date:	<input type="text"/>

Paint

Condition	Adequate	<input type="text"/>
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	<input type="text"/>			
Corrective Action:	<input type="text"/>			Date: <input type="text"/>

Venting:

Yes/No	NO	<input type="text"/>	
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

Flaring:

Type	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

Inspected Facilities									
Facility ID:	271038	Type:	WELL	API Number:	045-09796	Status:	PR	Insp. Status:	PR

--

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	286029	1433459	
	286029	1433459	